



Revision Guide for AMD Family 10h Processors

Publication # 41322 Revision: 3.00 Issue Date: September 2007

© 2007 Advanced Micro Devices, Inc. All rights reserved.

The contents of this document are provided in connection with Advanced Micro Devices, Inc. (“AMD”) products. AMD makes no representations or warranties with respect to the accuracy or completeness of the contents of this publication and reserves the right to make changes to specifications and product descriptions at any time without notice. No license, whether express, implied, arising by estoppel or otherwise, to any intellectual property rights is granted by this publication. Except as set forth in AMD’s Standard Terms and Conditions of Sale, AMD assumes no liability whatsoever, and disclaims any express or implied warranty, relating to its products including, but not limited to, the implied warranty of merchantability, fitness for a particular purpose, or infringement of any intellectual property right.

AMD’s products are not designed, intended, authorized or warranted for use as components in systems intended for surgical implant into the body, or in other applications intended to support or sustain life, or in any other application in which the failure of AMD’s product could create a situation where personal injury, death, or severe property or environmental damage may occur. AMD reserves the right to discontinue or make changes to its products at any time without notice.

Trademarks

AMD, the AMD Arrow logo, AMD Opteron and combinations thereof, are trademarks of Advanced Micro Devices, Inc.

HyperTransport is a licensed trademark of the HyperTransport Technology Consortium.

Other product names used in this publication are for identification purposes only and may be trademarks of their respective companies.

Revision History

Date	Revision	Description
September 2007	3.00	Initial public release.

Revision Guide for AMD Family 10h Processors

The purpose of the *Revision Guide for AMD Family 10h Processors* is to communicate updated product information to designers of computer systems and software developers. This revision guide includes information on the following products:

- Dual-Core AMD Opteron™ processor
- Quad-Core AMD Opteron™ processor
- Embedded AMD Opteron™ processor

This guide consists of three major sections:

- **Processor Identification:** This section, starting on page 5, shows how to determine the processor revision, program and display the processor name string, and construct the processor name string.
- **Product Errata:** This section, starting on page 12, provides a detailed description of product errata, including potential effects on system operation and suggested workarounds. An erratum is defined as a deviation from the product's specification, and as such may cause the behavior of the processor to deviate from the published specifications.
- **Documentation Support:** This section, starting on page 33, provides a listing of available technical support resources.

Revision Guide Policy

Occasionally, AMD identifies product errata that cause the processor to deviate from published specifications. Descriptions of identified product errata are designed to assist system and software designers in using the processors described in this revision guide. This revision guide may be updated periodically.

Processor Identification

This section shows how to determine the processor revision, program and display the processor name string, and construct the processor name string.

Revision Determination

Figure 1 shows the format of the value returned in EAX by CPUID Function 1.




Figure 1. Format of CPUID Value Returned by Function 1

Table 1 shows the identification number returned by the CPUID instruction for each revision of the processor.

Table 1. CPUID Values for AMD Family 10h Processor Revisions

Revision	CPUID Function 1 EAX Value		
	Quad-Core AMD Opteron™ Processor	Dual-Core AMD Opteron™ Processor	Embedded AMD Opteron™ Processor
DR-BA	00100F2Ah	00100F2Ah	00100F2Ah
DR-B2	00100F22h	00100F22h	00100F22h

Programming and Displaying the Processor Name String

This section, intended for BIOS programmers, describes how to program and display the 48-character processor name string that is returned by CPUID Fn8000_000[4:2]. The hardware or cold reset value of the processor name string is 48 ASCII NUL characters, so the BIOS must program the processor name string before any general purpose application or operating system software uses the extended functions that read the name string. It is common practice for the BIOS to display the processor name string and model number whenever it displays processor information during boot up.

Note: *Motherboards that do not program the proper processor name string and model number will not pass AMD validation and will not be posted on the AMD Recommended Motherboard Web site.*

The name string must be ASCII NUL terminated and the 48-character maximum includes that NUL character.

The processor name string is programmed by MSR writes to the six MSR addresses covered by the range C001_00[35:30]h. Refer to the *BIOS and Kernel Developer's Guide (BKDG) for AMD Family 10h Processors*, order # 31116, for the format of how the 48-character processor name string maps to the 48 bytes contained in the six 64-bit registers of MSR C001_00[35:30]h.

The processor name string is read by CPUID reads to a range of CPUID functions covered by CPUID Fn8000_000[4:2]. Refer to CPUID Fn8000_000[4:2] in the *BIOS and Kernel Developer's Guide (BKDG) for AMD Family 10h Processors*, order # 31116, for the 48-character processor name string mapping to the 48 bytes contained in the twelve 32-bit registers of CPUID Fn8000_000[4:2].

Constructing the Processor Name String

This section describes how to construct the processor name string. BIOS uses the following fields to create the name string:

- **BrandId[15:0]** is from CPUID Fn8000_0001_EBX.
 - **String1[3:0]** is defined to be BrandID[14:11]. This field is an index to a string value used to create the processor name string. The definition of the string1 values are provided in Table 3 on page 8.
 - **String2[3:0]** is defined to be BrandID[3:0]. This field is an index to a string value used to create the processor name string. The definition of the string1 values are provided in Table 4 on page 8.
 - **Model[6:0]** is defined to be BrandID[10:4]. This field is used to create the model number in the name string. The model field represents a numerical model number which should be converted to ASCII for display of the model number.
 - **Pg[0]** is defined to be BrandID[15]. This field is used to index the appropriate page for the String1, String2, and Model values.

- PkgTyp[3:0] is from CPUID Fn8000_0001_EBX. This field specifies the package type as defined in the *BIOS and Kernel Developer's Guide (BKDG) for AMD Family 10h Processors*, order #31116, and is used to index the appropriate string tables from Table 2.
- NC[7:0] is from CPUID Fn8000_0008[ECX]. This field identifies how many physical cores are present as defined in the *BIOS and Kernel Developer's Guide (BKDG) for AMD Family 10h Processors*, order #31116, and is used to index the appropriate strings from Table 3 on page 8, and Table 4 on page 8.

The name string is formed as follows:

1. Translate Model[6:0] into an ASCII value (*Model*), model numbers will range from 01-99. Model numbers less than 10 should include a leading zero, e.g., 09.
2. If Model[6:0] = 00h, skip steps 3 through 6 and program the name string as follows:
 - If Pg[0] = 0, *Name string = AMD Engineering Sample*
 - Else If Pg[0] = 1, *Name string = AMD Thermal Test Kit*
3. Else select the appropriate string tables based on PkgTyp[3:0] from Table 2
4. Index into the referenced tables using String1[3:0], String2[3:0], and NC[7:0] to obtain the *String1* and *String2* values.
5. If *String1* is an undefined value skip step 6 and program the name string as follows:
 - Name String = AMD Processor Model Unknown*
6. Else concatenate the strings with the two character ASCII translation of Model[3:0] from step 1 to obtain the name string as follows:
 - If *String2* is undefined, *Name string = String1, Model*
 - Else, *Name string = String1, Model, String2*

Table 2. String Table Reference Per Package Type

PkgTyp [3:0]	String1 Table	String2 Table
0h	Table 3 on page 8	Table 4 on page 8
1h-Fh	Reserved	Reserved

Table 3. String1 Values for Socket Fr2 (1207) Processors

Pg[0]	NC [7:0]	String [3:0]	Value	Note	Description
0b	01h	0h	Dual-Core AMD Opteron(tm) Processor 83	-	MP Server
0b	01h	1h	Dual-Core AMD Opteron(tm) Processor 23	-	DP Server
0b	03h	0h	Quad-Core AMD Opteron(tm) Processor 83	-	MP Server
0b	03h	1h	Quad-Core AMD Opteron(tm) Processor 23	-	DP Server
0b	03h	2h	Embedded AMD Opteron(tm) Processor 83	-	MP Server
0b	03h	3h	Embedded AMD Opteron(tm) Processor 23	-	DP Server
0b	03h	4h	Embedded AMD Opteron(tm) Processor 13	-	UP Server
All other values			AMD Processor Model Unknown	-	

Table 4. String2 Values for Socket Fr2 (1207) Processors

Pg[0]	NC [7:0]	String [3:0]	Value	Note	Description
0b	xxh	0Ah	SE	1	
0b	xxh	0Bh	HE	1	
0b	xxh	0Ch	EE	1	
0b	xxh	0Fh		2	
All other values			Reserved	-	

1. The string includes a space as the leading character.

2. The String2 index 0Fh is defined as an empty string, i.e., no suffix.

F4x164 Fixed Errata Register

Communicating the status of an erratum requiring a workaround within a stepping of a processor family is necessary in certain circumstances. F4x164 is used to communicate the status of such an erratum fix so that BIOS or system software can determine the necessity of applying the workaround. Under these circumstances, the erratum workaround references the specified bit to enable software to test for the presence of the erratum. The revisions of a processor, prior to the definition of a bit may not be affected by the erratum. Therefore, software should use the stepping as the first criteria to identify the applicability of an erratum. Once defined, the definition of the status bit will persist within the family of processors.

Bits	Description
31:0	0000_0000h. Reserved.

MSRC001_0140 OS Visible Work-around MSR0 (OSVW_ID_Length)

This register is used to specify the number valid status bits within the OS Visible Work-around status registers as defined in *AMD64 Architecture Programmer's Manual Documentation Updates*, order# 33633.

The default value of this register is 0000_0000_0000_0000h.

BIOS shall program the specified length as specified in Table 5 prior to hand-off to the OS.

Bits	Description
63:16	Reserved.
15:0	OSVW_ID_Length: OS visible work-around ID length. Read-write

Table 5. OSVW_ID_Length Per Processor Revision

MSRC001_1040 Bits	Revision Number	
	DR-BA	DR-B2
15:0	0000h	0000h

MSRC001_0141 OS Visible Work-around MSR1 (OSVW_Status)

This register provides the status of the known OS visible errata as defined in *AMD64 Architecture Programmer's Manual Documentation Updates*, order# 33633. Known errata are assigned an OSVW_ID corresponding to the bit position within the valid status field.

Operating system software should use MSRC001_0140 to determine the valid length of the bit status field. For all valid status bits: 1=Hardware contains the erratum, and an OS software work-around is required. 0=Hardware has corrected the erratum, so an OS software work-around is not necessary.

The reset default value of this register is 0000_0000_0000_0000h.

BIOS shall program the state of the valid status bits as specified in Table 6 prior to hand-off to the OS.

Bits	Description
63:0	OsvwStatusBits: OS visible work-around status bits. Read-write.

Table 6. Cross Reference of Product Revision To OSVW_ID

MSRC001_1041 Bits	Revision Number	
	DR-BA	DR-B2
63:0	0000_ 0000_ 0000_ 0000h	0000_ 0000_ 0000_ 0000h

Product Errata

This section documents product errata for the processors. A unique tracking number for each erratum has been assigned within this document for user convenience in tracking the errata within specific revision levels. Table 7 cross-references the revisions of the part to each erratum. An “X” indicates that the erratum applies to the revision. The absence of an “X” indicates that the erratum does not apply to the revision. An “*” indicates advance information that the erratum has been fixed but not yet verified. “No fix planned” indicates that no fix is planned for current or future revisions of the processor.

Note: *There may be missing errata numbers. Errata that have been resolved from early revisions of the processor have been deleted, and errata that have been reconsidered may have been deleted or renumbered.*

Table 7. Cross-Reference of Product Revision to Errata

No.	Errata Description	Revision Number	
		DR-BA	DR-B2
57	Some Data Cache Tag Eviction Errors Are Reported As Snoop Errors	No fix planned	
60	Single Machine Check Error May Report Overflow	No fix planned	
77	Long Mode CALLF or JMPF May Fail To Signal GP When Callgate Descriptor is Beyond GDT/LDT Limit	No fix planned	
178	Default RdPtrInit Value Does Not Provide Sufficient Timing Margin	X	X
244	A DIV Instruction Followed Closely By Other Divide Instructions May Yield Incorrect Results	X	X
246	Breakpoint Due to An Instruction That Has An Interrupt Shadow May Be Delivered to the Hypervisor	X	X
248	INVLPGA of A Guest Page May Not Invalidate Splintered Pages	X	*
254	Internal Resource Livelock Involving Cached TLB Reload	X	X
260	REP MOVS Instruction May Corrupt Source Address	X	X
261	Processor May Stall Entering Stop-Grant Due to Pending Data Cache Scrub	No fix planned	
263	Incompatibility With Some DIMMs Due to DQS Duty Cycle Distortion	X	X
264	Incorrect DRAM Data Masks Asserted When DRAM Controller Data Interleaving Is Enabled	X	X
269	ITT Specification Exceeded During Power-Up Sequencing	No fix planned	
273	Lane Select Function Is Not Available for Link BIST on 8-Bit HyperTransport™ Links In Ganged Mode	X	X
274	IDDIIO Specification Exceeded During Power-Up Sequencing	X	

Table 7. Cross-Reference of Product Revision to Errata (Continued)

No.	Errata Description	Revision Number	
		DR-BA	DR-B2
278	Incorrect Memory Controller Operation In Ganged Mode	X	
279	HyperTransport™ Link RTT and RON Specification Violations	X	
280	Time Stamp Counter May Yield An Incorrect Value	X	X

Table 8 cross-references the errata to each processor segment. An empty cell signifies that the erratum does not apply to the processor segment. “X” signifies that the erratum applies to the processor segment. “N/A” signifies that the erratum does not apply to the processor segment due to the silicon revision.

Table 8. Cross-Reference of Errata to Processor Segments

Errata Number	Quad-Core AMD Opteron™ Processor	Dual-Core AMD Opteron™ Processor	Embedded AMD Opteron™ Processor
57	X	X	X
60	X	X	X
77	X	X	X
178	X	X	X
244	X	X	X
246	X	X	X
248	X	X	X
254	X	X	X
260	X	X	X
261	X	X	X
263	X	X	X
264	X	X	X
269	X	X	X
273	X	X	X
274	X	X	X
278	X	X	X
279	X	X	X
280	X	X	X

57 Some Data Cache Tag Eviction Errors Are Reported As Snoop Errors

Description

In some cases, the machine check error code on a data cache (DC) tag array parity error erroneously classifies an eviction error as a snoop error.

The common cases of cache line replacements and external probes are classified correctly (as eviction and snoop respectively). The erroneous cases occur when a tag error is detected during a DC eviction that was generated by a hardware prefetch, a cache line state change operation, or a number of other internal microarchitectural events. In such cases, the error code logged in the DC Machine Check Status register (MC0_STATUS, MSR 0x401) erroneously indicates a snoop error.

Potential Effect on System

Internally detected DC tag errors may be reported to software as having been detected by snoops. Depending upon machine check software architecture, the system response to such errors may be broader than necessary.

Suggested Workaround

None required.

Fix Planned

No

60 Single Machine Check Error May Report Overflow

Description

A single parity error encountered in the data cache tag array may incorrectly report the detection of multiple errors, as indicated by the overflow bit of the DC Machine Check Status register (bit 62 of MSR 0x401).

Potential Effect on System

System software may be informed of a machine check overflow when only a single error was actually encountered.

Suggested Workaround

Do not rely on the state of the OVER bit in the DC Machine Check Status register.

Fix Planned

No

77 Long Mode CALLF or JMPF May Fail To Signal GP When Callgate Descriptor is Beyond GDT/LDT Limit

Description

If the target selector of a far call or far jump (CALLF or JMPF) instruction references a 16-byte long mode system descriptor where any of the last 8 bytes are beyond the GDT or LDT limit, the processor fails to report a General Protection fault.

Potential Effect on System

None expected, since the operating system typically aligns the GDT/LDT limit such that all descriptors are legal. However, in the case of erroneous operating system code, the above described GP fault will not be signaled, resulting in unpredictable system failure.

Suggested Workaround

None required, it is anticipated that long mode operating system code will ensure the GDT and LDT limits are set high enough to cover the larger (16-byte) long mode system descriptors.

Fix Planned

No

178 Default RdPtrInit Value Does Not Provide Sufficient Timing Margin

Description

Insufficient separation of the read pointer and write pointer in the synchronization FIFO can lead to setup violations in the transmit FIFO.

Potential Effect on System

The setup violations may lead to data corruption.

Suggested Workaround

BIOS should program F2x[1, 0]78[3:0] (RdPtrInit) to 4'h5.

Fix Planned

Yes

244 A DIV Instruction Followed Closely By Other Divide Instructions May Yield Incorrect Results

Description

A DIV instruction with a divisor less than 64 that is followed in close proximity by a DIV, IDIV, or AAM instruction may produce incorrect results.

Potential Effect on System

Possible data corruption.

Suggested Workaround

Contact your AMD representative for information on a BIOS update.

Fix Planned

Yes

246 Breakpoint Due to An Instruction That Has An Interrupt Shadow May Be Delivered to the Hypervisor

Description

A #DB exception occurring in guest mode may be delivered in the host context under the following conditions:

- A trap-type #DB exception is generated in guest mode during execution of an instruction with an interrupt shadow, and
- The instruction that generated the exception is immediately followed by an instruction resulting in #VMEXIT.

Potential Effect on System

Unpredictable results due to an unexpected #DB exception.

Suggested Workaround

The hypervisor should have a valid interrupt gate in the IDT of the #DB handler entry and the handler must be able to determine that this event has occurred. If the event is detected, the handler should execute an IRET back to the hypervisor; one method that could be used to evaluate for this condition is to compare the RIP pushed on the stack to the RIP of the instruction following VMRUN, if they are equivalent then this event has occurred.

Fix Planned

Yes

248 INVLPGA of A Guest Page May Not Invalidate Splintered Pages

Description

When an address mapped by a guest uses a larger page size than the host, the TLB entry created uses the size of the smaller page; this is referred to as page splintering. TLB entries that are the result of page splintering may not be invalidated when the large page is invalidated in the guest using INVLPGA.

Potential Effect on System

Unpredictable system behavior may result due to inconsistent entries in the TLB.

Suggested Workaround

The hypervisor should always intercept INVLPGA instructions. On returning to the guest from the INVLPGA intercept the hypervisor should set `TLB_Control = 1` in the VMCB to ensure correctness.

Fix Planned

Yes

254 Internal Resource Livelock Involving Cached TLB Reload

Description

Under a highly specific and detailed set of conditions, an internal resource livelock may occur between a TLB reload and other cached operations.

Potential Effect on System

The system may hang.

Suggested Workaround

BIOS should apply the workaround based on the extended model, base model, and stepping reported by CPUID Fn8000_0001 as described in the following table:

CPUID Fn8000_0001_EAX[19:16] (Extended Model)	CPUID Fn8000_0001_EAX[7:4] (Base Model)	CPUID Fn8000_0001_EAX[3:0] (Stepping)	HWCR[3] (MSRC001_0015h)	BU_CFG[1] (MSRC001_1023h)	BU_CFG[21] (MSRC001_1023h)
0h	2h	Ah	0b	0b	1b
0h	2h	2h	0b	0b	1b

Fix Planned

Yes

260 REP MOVS Instruction May Corrupt Source Address

Description

The processor may corrupt the source address for REP MOVS instructions using 16- or 32-bit addressing when a fault occurs on the first iteration and ECX is greater than 255 and EDI equals 0.

Potential Effect on System

Unpredictable system behavior.

Suggested Workaround

Contact your AMD representative for information on a BIOS update.

Fix Planned

Yes

261 Processor May Stall Entering Stop-Grant Due to Pending Data Cache Scrub

Description

The processor may stall if a correctable error is identified by the data cache scrubber within a small window of time before the processor enters a stop-grant state when another scrub is pending.

Potential Effect on System

The system may hang.

Suggested Workaround

BIOS should set MSRC001_1022[24].

Fix Planned

No fix planned.

263 Incompatibility With Some DIMMs Due to DQS Duty Cycle Distortion

Description

Some DDR2 DIMMs exhibit a duty cycle distortion on the first DQS pulse of an incoming read request which may cause the processor's DDR interface to miss a beat of data in a read burst.

Potential Effect on System

Undefined system behavior due to incorrect read data.

Suggested Workaround

BIOS should execute the following sequence prior to the DRAM initialization for DDR2-533 and DDR2-667:

1. Write 00000800h to F2x[1, 0]9C_xD040F30.
2. Execute the DRAM Initialization sequence as defined in the *BIOS and Kernel Developer's Guide for AMD Family 10h Processors*, order# 31116.

In addition, during DQS position training BIOS should set the DRAM read DQS timing control loop range to 32 instead of 64.

Fix Planned

Yes.

264 Incorrect DRAM Data Masks Asserted When DRAM Controller Data Interleaving Is Enabled

Description

The processor may incorrectly assert the DRAM data masks for writes less than a cacheline when DRAM controller data interleaving is enabled.

Potential Effect on System

Data corruption.

Suggested Workaround

BIOS should set MSRC001_001F[36] (DisDatMsk) to 1b when F2x110[5] (DctDatIntLv) is set to 1b.

Fix Planned

Yes.

269 ITT Specification Exceeded During Power-Up Sequencing

Description

Processor current consumption may exceed the ITT maximum specified for C0/S0 operation if the VTT voltage regulator is enabled before the VDDIO voltage regulator and the VDDIO regulator enables a low resistance path to VSS while $V_{TT} - V_{DDIO} > 400$ mV.

Potential Effect on System

The VTT voltage regulator may shut down if ITT exceeds the platform design limit.

Suggested Workaround

None required if either of the following are true:

- The VTT regulator is enabled at the same time or after the VDDIO regulator.
- The VDDIO regulator does not enable a low resistance path to VSS while $V_{TT} - V_{DDIO} > 400$ mV.

For affected systems, the VTT voltage regulator should be enabled at the same time or after the VDDIO voltage regulator during power-up power sequencing. Existing specifications limiting the VDDIO to VTT relationship must be maintained.

Fix Planned

No

273 Lane Select Function Is Not Available for Link BIST on 8-Bit HyperTransport™ Links In Ganged Mode

Description

The link BIST engine incorrectly initiates tests on sublink 1 rather than sublink 0 under the following conditions:

- The HyperTransport™ link is configured as an 8-bit link in ganged mode,
- LaneSel[1], F0x[18C:170][13], is set to 1b,
- BistEn, F0x[18C:170][10], is set to 1b, and
- BIST is initiated by assertion of warm reset or a LDTSTOP_L disconnect.

Potential Effect on System

No impact to normal operational mode; however, the lane select function is not available for testing asymmetric links or isolation of errors to the uplink or downlink on symmetric links.

Suggested Workaround

None.

Fix Planned

Yes

274 IDDIO Specification Exceeded During Power-Up Sequencing

Description

Processor current consumption may exceed the IDDIO maximum specified for C0/S0 operation during power-up sequencing.

Potential Effect on System

None expected if the VDDIO voltage regulator is sourced by a RUN (running) plane from the power supply during power-up sequencing. Otherwise, during power-up sequencing the VDDIO voltage regulator may shut down if IDDIO exceeds the platform budget or the power supply may shut down if the SUS (suspend) rail current capacity is exceeded.

Suggested Workaround

Three options exist to ensure the VDDIO voltage regulator is sourced with sufficient current during processor power-up sequencing:

1. Enable the VDDIO voltage regulator after POWER_GOOD is asserted from the high-current (RUN) source rail.
2. Provide a path for a high-current (RUN) rail to source current to the VDDIO voltage regulator prior to POWER_GOOD assertion from the high-current (RUN) rail. This solution assumes the high-current (RUN) rail is enabled early enough relative to enabling the VDDIO voltage regulator.
3. Choose a power supply with increased capacity for the rail sourcing the VDDIO voltage regulator during power-up sequencing. The capacity required is system specific and should allocate 7 amps per processor in the power budget. The following is an example of a supply current capacity calculation assuming a 5 V suspend rail and 3 W rest of system power for a single-processor system. Other platform-specific factors such as power supply or regulator efficiencies should also be considered.
 - Rest of system (non-processor) power = 3 W
 - Processor power = 7 A/processor * 1 processor * 1.8 V = 12.6 W
 - Source rail capacity = (rest of system power + processor power) / source rail voltage; (3 W + 12.6 W) / 5 V = 3.12 A

Fix Planned

Yes

278 Incorrect Memory Controller Operation In Ganged Mode

Description

The DRAM controller 0 (DCT0) and DRAM controller 1 (DCT1) refresh counters may not be initialized to the same value using hardware controlled DRAM initialization when operating in ganged mode.

Potential Effect on System

Incorrect memory controller operation.

Suggested Workaround

BIOS should apply the following workaround prior to DRAM training when using hardware-controlled DRAM initialization and F2x110[4] (DctGangEn) is set to 1b.

1. Disable automatic refresh cycles by setting F2x08C[18] (DisAutoRefresh) to 1b.
2. Begin DRAM initialization by setting F2x090[0] to 1b.
3. Poll F2x090[0] until it reads 0b then wait at least 50 microseconds.
4. Enable automatic refresh cycles by clearing F2x08C[18] (DisAutoRefresh) to 0b.
5. Disable automatic refresh cycles by setting F2x08C[18] (DisAutoRefresh) to 1b.
6. Enable automatic refresh cycles by clearing F2x08C[18] (DisAutoRefresh) to 0b.
7. Begin DRAM training.

In addition, when resuming from S3, BIOS should apply the following workaround.

1. Disable automatic refresh cycles by setting F2x08C[18] (DisAutoRefresh) to 1b.
2. Initiate exit from self refresh by setting F2x090[1] to 1b.
3. Poll F2x090[1] until it reads 0b then wait at least 50 microseconds.
4. Enable automatic refresh cycles by clearing F2x08C[18] (DisAutoRefresh) to 0b.
5. Disable automatic refresh cycles by setting F2x08C[18] (DisAutoRefresh) to 1b.
6. Enable automatic refresh cycles by clearing F2x08C[18] (DisAutoRefresh) to 0b.

Fix Planned

Yes

279 HyperTransport™ Link R_{TT} and R_{ON} Specification Violations

Description

The R_{TT} and R_{ON} specifications for the HyperTransport™ link may be violated on some processor revisions.

Potential Effect on System

These violations do not result in any other HyperTransport™ link electrical specification violations. There are no known functional failures related to this problem.

Suggested Workaround

None required.

Fix Planned

Yes.

280 Time Stamp Counter May Yield An Incorrect Value

Description

Reads of the time stamp counter may yield an inconsistent result.

Potential Effect on System

Undefined behavior for software that relies on a continuously increasing time stamp counter value.

Suggested Workaround

Contact your AMD representative for information on a BIOS upgrade.

Fix Planned

Yes.

Documentation Support

The following documents provide additional information regarding the operation of the processor:

- *BIOS and Kernel Developer's Guide (BKDG) for AMD Family 10h Processors*, order# 31116
- *AMD64 Architecture Programmer's Manual Volume 1: Application Programming*, order# 24592
- *AMD64 Architecture Programmer's Manual Volume 2: System Programming*, order# 24593
- *AMD64 Architecture Programmer's Manual Volume 3: General-Purpose and System Instructions*, order# 24594
- *AMD64 Architecture Programmer's Manual Volume 4: 128-Bit Media Instructions*, order# 26568
- *AMD64 Architecture Programmer's Manual Volume 5: 64-Bit Media and x87 Floating-Point Instructions*, order# 26569
- *AMD CPUID Specification*, order# 25481

See the AMD Web site at www.amd.com for the latest updates to documents.